


Latest Release of the Contigo System

The latest release of the Contigo System was completed on Thursday June 20, 2013. Please see below for a brief description of the enhancements included in this release.

Important Notes

1. If you continue to use Flash technology for viewing maps in the portal, FlashPlayer 11.1+ is required to be installed in your browser. Please ensure that Flash is up to date on your system.
2. To ensure that all portal features function correctly, it is recommended that you clear your browser's cookies and cache. For assistance, please visit http://www.contigo.com/clear_browser_cache.html.

Feature	Description
6550/6551 – Beacon Replacement Tools 	<p>This release allows partners to easily replace existing beacons with the newer 6550 and 6551 HSPA beacon models, retaining scenario configurations* as well as historical data. The following replacement paths are available in the release:</p> <ul style="list-style-type: none"> • 6200 to 6550/6551 • 6100 to 6550/6551 • 6150/6151 to 6550/6551 • 6450 to 6550/6551 • 6550/6551 to 6450 • 6550/6551 to 6550/6551 <p>* Note that not all features are compatible across all beacon models, and certain scenarios may not be migrated to the replacement beacon.</p>
Other Updates and Bug Fixes	<p>The following issues are addressed in this system release:</p> <ul style="list-style-type: none"> • revised 6151 programming to prevent occasional delayed or missing start and stop events • upgraded SSL certificates to ensure continued secure portal access

In addition to the features above, this release will also include other minor bug fixes and enhancements.

If you have any questions or comments, please do not hesitate to contact us at support@contigo.com.

Best regards,
The Contigo Team