






Contigo Systems announces end of life dates and action plans for Contigo beacons 6200, 5250, DS500, GGE-7100, 1200 & 5200.

<u>Beacon</u>	<u>Image</u>	<u>Date & Action Plan</u>
6200, 5250		<p>Effective immediately: The manufacturer is no longer offering repair services for out of warranty beacons. Please note, warranties will still be honored, technical support will still be provided and existing beacons will continue to run as normal on the Contigo platform.</p> <p>June 30, 2012: Partners may purchase a refurbished beacon as replacement for an out of warranty failure for \$75 until June 30, 2012.</p>
DS500		<p>Effective immediately: The manufacturer is no longer offering repair services for out of warranty beacons. Please note, warranties will still be honored, technical support will still be provided and existing beacons will continue to run as normal on the Contigo platform.</p>
GGE-7100		<p>January 1, 2012: Technical support requests will no longer be accepted for this beacon. Please note, service on the Contigo platform will continue beyond this date. In addition, reactivation requests will also be accepted beyond this date.</p>
1200 & 5200		<p>January 1, 2012: Technical support and reactivation requests will no longer be accepted for this beacon. Please note, service on the Contigo platform will continue beyond this date.</p>

Contigo Systems announces product change for 8200, 8210, 8210P.

8200, 8210, 8210P		<p>Effective immediately: The 1800mAh battery is no longer available for order, and it now comes standard with the 3600mAh battery. The 3600mAh battery typically provides 14 to 30 days of battery life depending on frequency of location reports.</p> <p>This beacon with the 3600mAh battery is still available for sale, and warranties will still be honored, technical support will still be provided and existing beacons will continue to run as normal on the Contigo platform.</p>
-------------------	---	--

Please also note, as previously announced the 1500, 1600, 6100, 8100 & 8110 beacons are no longer available for purchase. Hardware warranties for these beacons will continue to be honored and existing beacons will continue to run as normal on the Contigo platform.