

## Latest Release of the Contigo System

The latest release of the Contigo System will be completed on Thursday October 20, 2016. Please see below for a brief description of the enhancements included in this release.

Feature	Description
<b>Contigo 6601 HOS Device</b> 	<p>Contigo is pleased to add the 6601 HOS device to its expanding range of high-performance fleet beacons. Designed to plug directly into a J1939 port, the 6601 will support data received directly from the vehicle ECM, and will connect to ELD compliant handheld devices via Bluetooth.</p> <p>In addition to ELD compliance, the device supports all existing fleet capabilities expected from Contigo devices, including:</p> <ul style="list-style-type: none"> <li>• Real-time location</li> <li>• Route logs</li> <li>• Ignition on/off</li> <li>• Start and stop movement</li> <li>• Circular and Polygon zone notifications</li> <li>• Arm where parked</li> <li>• Power cut notification</li> <li>• Speed notifications (including posted speeds)</li> <li>• Speed in zone</li> <li>• Idle report and notification</li> <li>• Driver behavior</li> <li>• J1939 DTC events</li> </ul> <p>Optional add-ons include:</p> <ul style="list-style-type: none"> <li>• Driver ID</li> <li>• Temperature sensor</li> <li>• Inputs and Outputs</li> <li>• Dispatch &amp; Navigation</li> </ul>

In addition to the features above, this release will also include other minor bug fixes and enhancements.

If you have any questions or comments, please do not hesitate to contact us at [support@contigo.com](mailto:support@contigo.com).

Best regards,  
**The Contigo Team**